

Technical Bulletin

AC Central Power Supply

This Technical Bulletin explains the replacement of a label that states the use of Class II wiring. This bulletin effects all model PDI-772UL or PDI-773UL manufactured before February 1, 2003.



Communication
Systems, Inc.
40 Greenwood Lane
Springboro, Ohio
45066

PH: 937-743-6010
FX: 937-743-5664

<http://www.pdiarm.com>

PDI-772UL
PDI-773UL
Class II Label Replacement

CLASS II Label Replacement

This Technical Bulletin explains the replacement of a label that states the use of Class II wiring. This bulletin effects the model PDI-772UL or PDI-773UL manufactured before February 1, 2003.



Note: not all central power supplies are missing this label.


A problem has been brought to the attention of PDI regarding a missing label on the PDI-772UL central power supply. This bulletin will explain the requirement for the label and how to replace the label in the field.

Overview

The PDI-772UL and PDI-773UL central power supply is designed to mount in a utility closet and remotely power individual small screen swing-arm televisions. The use of appropriate cable between the central and each television is critical. The Class II output label states specific cables and output levels for the supply.

Procedure

1. Open the front cover of the central. Inspect the AC/RF distribution box for the missing label. The distribution box will have a single row of 10 "F" outputs for the PDI-772UL or a double row of 10 "F" outputs for the PDI-773UL model. The label begins with the words "CLASS 2 WIRING MAY BE USED."
2. If this label is missing replace the label with the one attached to this bulletin.



For More Information

If you have questions, please contact PDI's Engineering department at 937-743-6010 Extension 252.